APPENDIX 3

PERFORMANCE MEASURES - OBJECTIVES

SACRAMENTO DISTRICT ENGINEERING DIVISION

PERFORMANCE MEASURES - OBJECTIVES

We pledge to implement the following performance measures to obtain the specified objectives:

Brain W. Doyle	Jugary motani
Brian W. Doyle, PE Carl Van Dam, PE	Shigeru Fujitani, RA Colored Allocas Edward A. Ketchum, PE
11221	Jand a Rokott
Frank W. Winton, PE John R. Hess, PE	Thomas W. Ju
Trahast	Thomas W. Fea, RG
Frank Y.F. Fong, PE Kenneth P. Kuhn, PE	Milliam D. Mullery
Kenneth P. Kuhn, PE	William D. Mullery, PE
Ronald F. Muller, PE	Roger C. Henderson, PE

Thomas E. Nissen, PE

Arthur D. Chan; PE

Ralph F. Buell, RA

Steven P. Freitas, PE

Steven P. Freitas, PE

ENGINEERING DIVISION FY2000 PERFORMANCE MEASURES - OBJECTIVE #1

ALIGN FOR SUCCESS OPTIMIZE OUR ORGANIZATION

FLEXIBLE & EFFICIENT PRODUCT DELIVERY PROCESSES THAT ARE BEING CONTINUOUSLY IMPROVED

We must continually evaluate, communicate, and update our policies and procedures to ensure that we have the best product delivery system possible to meet customer expectations.

PERFORMANCE MEASURE	ACTIONS
Measure: Obtain ISO 9001 certification in FY 00	Train Internal Auditors
	™ Do 1 st Semiannual internal audit
Baseline: Certify Audit NLT Sept. 2000	Do 1 st round Corrective actions on nonconformances found
	™ Do 2 nd Semiannual internal audit
Data Source: Corrective/Preventative action reports	Do 2 nd round corrective actions on nonconformances found
	Educate ED employees on number of nonconformances
Data Location: ET&S ISO Webbed pages	Identify preventative actions.
	Correct QM and EQPs to latest findings
Update Frequency: Surveillance Audits every 6 months	Conduct staff review to assure goals are achievable
& Quarterly Management Team meetings	Consultant performs comprehensive system review
	Registrar conducts system preassessment audit
	Registrar conducts compliance (certification) audit
	Continue audit cycle

ENGINEERING DIVISION FY2000 PERFORMANCE MEASURES – OBJECTIVE #2 SATISFY THE CUSTOMER DELIGHT OUR CUSTOMERS DELIGHTED CUSTOMERS

Customer identification is difficult and we do not actively seek customer input on our ongoing and completed products sufficiently. We must ask recipients and users of our products if their requirements are being met and evaluate the responses to determine how we can improve our product delivery.

PERFORMANCE MEASURE	ACTIONS
Measure: Customer Success surveys	PPMD to create new customer survey
	■ Evaluate and respond to customer feedback
Baseline: Existing HQ formatted surveys	Share survey results with ED employees
	Provide an incentive for customer to return completed survey
Data Source: PPMD	Achieve 75% return on surveys
	Consolidate ED customer survey responses over FY 00
Data Location: PPMD Files	■ Management team review responses ■ Make personal
	contacts on negative responses
Update Frequency: Create and deploy with each product	Follow-up corrective actions on negative responses
deliverable a new Engineering Division Customer Survey	
Measure: Cost growth during construction due to design	■ ET&S Support Unit to tabulate design deficiencies
deficiency	Management Team brief
Baseline: TBD	Follow-up corrective actions to incorporate into Lessons
	Learned
Data Source: Existing change orders	Review ARMS for systematic/repetitive issues
	■ Include C-O Division early in design processes
Data Location: ET&S Support Unit	Realistic schedules and resource management
	© Coordinate work scope with A-E before negotiations
Update Frequency: Quarterly	Set baseline and performance criteria

ENGINEERING DIVISION FY2000 PERFORMANCE MEASURES - OBJECTIVE #2 SATISFY THE CUSTOMER DELIGHT OUR CUSTOMERS DELIGHTED CUSTOMERS

Customer identification is difficult and we do not actively seek customer input on our ongoing and completed products sufficiently. We must ask recipients and users of our products if their requirements are being met and evaluate the responses to determine how we can improve our product delivery.

PERFORMANCE MEASURE	ACTIONS
Measure: % completion on schedule and within budget	■ Develop complete quality control plans and quality assurance
	plans
Baseline: TBD	Review schedule and resource utilization at each meeting
	Design and independent technical review teams provide
Data Source: Project Manager	complete requirements on work scope
	□ Document changes in scopes
Data Location: PROMIS/SOS PPMD records	Set baseline and performance criteria
Update Frequency: Quarterly	

ENGINEERING DIVISION FY2000 PERFORMANCE MEASURES - OBJECTIVE #3 BUILD THE TEAM BUILD THE REGIONAL TEAM EFFECTIVE TEAMWORK, INTERNALLY AND WITH OTHER DISTRICTS

Our resources (people, consultants, facilities, equipment, funds) are extremely valuable and are constantly being challenged by possible reductions, mandated use levels, and cost effectiveness. We must unify and improve our resource use through increased communication, timely acquisition, and cost reductions.

PERFORMANCE MEASURE	ACTIONS
Measure: Tri-Service CADD Standards Compliance	Evaluate each Electronic Bid Set deliverable for compliance
Baseline: TBD	Address specific non-conformities to project delivery team Progress report to management team Nov 2000
Data Source: AutoCAD/MicroStation native project files	
Data Location: ET&S CADD Manager	
Update Frequency: Semi-Annually	

ENGINEERING DIVISION FY2000 PERFORMANCE MEASURES - OBJECTIVE #3 BUILD THE TEAM BUILD THE REGIONAL TEAM EFFECTIVE TEAMWORK, INTERNALLY AND WITH OTHER DISTRICTS

Our resources (people, consultants, facilities, equipment, funds) are extremely valuable and are constantly being challenged by possible reductions, mandated use levels, and cost effectiveness. We must unify and improve our resource use through increased communication, timely acquisition, and cost reductions.

PERFORMANCE MEASURE	ACTIONS
Measure: Number of Partnered/Brokered projects with other	Search for appropriate Customer Orders to determine existing
Districts	number of partnered projects.
	Brief employees on Outreach as scheduled
Baseline: TBD	Report to management team Nov 2000 # brokered projects
	Discuss methods to increase projects partnered with others
Data Source: CEFMS Customer Orders	Set baseline and performance criteria
Data Location: PPMD, Budgets/Reports	
Update Frequency: Quarterly	

ENGINEERING DIVISION FY2000 PERFORMANCE MEASURES - OBJECTIVE #4 ENHANCE CAPABILITIES

AGGRESSIVELY PURSUE THE CORPS STRATEGIC VISION PARTNERSHIP WITH HIGHER HQ ON IMPLEMENTATION OF POLICIES & REGULATIONS

Our staff capabilities must be highlighted to higher HQ through increased brokering of our expertise.

PERFORMANCE MEASURE	ACTIONS
Measure: Number of requests from other agencies for specific expertise	Develop form to report non-District staff usage by others (e.g.: John Hess, long term & Steven Freitas, SPECSINTACT TRY)
Baseline: TBD	Brief management team Nov 2000 Develop methods to encourage brokered expertise
Data Source: 1 st Line Supervisors	Set baseline and performance criteria
Data Location: Engineering Division Front Office	Partner with SPK Leaders Development Group on their project
Update Frequency: Semi-Annually	

ENGINEERING DIVISION FY2000 PERFORMANCE MEASURES - OBJECTIVE #5 SERVE THE ARMY

Our product delivery success is primarily measured by whether or not production is on time, within budget, and meets customer expectations. We must find ways to reduce the amount of time we take, the cost needed to complete our products, and still maintain the required quality levels.

PERFORMANCE MEASURE	ACTIONS
Measure: QA/QC compliance	Search ARMS BCOE reviews for non-conformities
Baseline: TBD	Include C-O Div on reporting non-conformities Report by categories the types of non-conformities 1st report Nov 2000
Data Source: ARMS	Solicit from management team methods to correct non- conforming products
Data Location: ET&S Support Unit	Brief Independent Technical Review teams on methods to correct
Update Frequency: Quarterly	Brief design teams and include as Lessons Learned feedback Set baseline and performance criteria
Measure: In-House management fees by % of A-E/service contract administration	Educate ED employees on measurement Periodic/regular resource planning reviews by management
Baseline: 40%	Identify CMR components that are regularly yellow or red Identify actions needed to achieve, and individuals involved
Data Source: PPMD Budget/Reports	
Data Location: PPMD	
Update Frequency: With upward reporting cycles	

ENGINEERING DIVISION FY2000 PERFORMANCE MEASURES - OBJECTIVE #5 SERVE THE ARMY

Our product delivery success is primarily measured by whether or not production is on time, within budget, and meets customer expectations. We must find ways to reduce the amount of time we take, the cost needed to complete our products, and still maintain the required quality levels.

PERFORMANCE MEASURE	ACTIONS
Measure: ED D.O. rate for Civil Works and Military	Share D.O. status quarterly to all levels of supervisors
	Identify opportunities for management personnel to cost to
Baseline: 1 st Quarter FY 00 rates	projects
	☐ Include all expected expenses in work scopes
Data Source: RMO	■ Identify portions with greatest impact, and opportunity to
	control
Data Location: Engineering Division Front Office	Review items for value added (i.e.: increase training?)
	■ Update mid-year budget
Update Frequency: Quarterly	Review past years for trends
	All levels accountable to the budget limits

ENGINEERING DIVISION FY2000 PERFORMANCE MEASURES - OBJECTIVE #6 INVEST IN PEOPLE

Our staff capabilities are constantly stretched through mission changes, personnel reductions, and multiple assignments. We must balance our staff availability, knowledge, and utilization with challenging assignments, proper training, and unique opportunities.

PERFORMANCE MEASURE	ACTIONS
Measure: Employee turnover rate and reasons for leaving	Develop out briefing form for departing employees
n	Track forms by categories
Baseline: TBD	Brief management team Nov 2000
Data Source: 52 actions	Develop Lessons Learned to share with all employees Aug 2000
But source. 32 detions	Set baseline and performance criteria
Data Location: Engineering Division Front Office	•
Update Frequency: Quarterly	
Measure: Awards/recognition from customers	Develop tracking form for 1 st line supervisors
	Report to management team Nov 2000 award to date
Baseline: TBD	Solicit opportunities to increase # of awards
	Brief all employees on # awards and how obtained
Data Source: New form TBD	Set baseline and performance criteria
Data Location: Engineering Division Front Office	
Data Location. Engineering Division Profit Office	
Update Frequency: Quarterly	

ENGINEERING DIVISION FY2000 PERFORMANCE MEASURES - OBJECTIVE #6 INVEST IN PEOPLE

Our staff capabilities are constantly stretched through mission changes, personnel reductions, and multiple assignments. We must balance our staff availability, knowledge, and utilization with challenging assignments, proper training, and unique opportunities.

PERFORMANCE MEASURE	ACTIONS
Measure: Number of new projects/tasks from strategic	Solicit Outreach Director for strategic customers list
customers	Solicit 1 st line supervisors for FY 00 new project strategic
p 11 mpp	customer project starts
Baseline: TBD	Report to management team Nov 2000
Data Source: 1 st line supervisors	Set baseline and performance criteria
Data Location: Outreach Office	
Update Frequency: Semi-annually	
Measure: Number of new customers	Solicit Outreach Director for new customers list
	Solicit 1 st line supervisors for FY 00 new customers
Baseline: TBD	Report to management team Nov 2000
Data Source: Contact Database	Set baseline and performance criteria
Data Location: Outreach Office	
Update Frequency: Semi-annually	

ENGINEERING DIVISION FY2000 PERFORMANCE MEASURES - OBJECTIVE #7 RESHAPE THE CULTURE

We need to measure our communications effectiveness of the Corps of Engineers Project Management Business Process and team collaboration to all our staff.

ACTIONS
Get District Internal survey and use/modify
Conduct 2nd baseline survey NLT 3 rd Quarter FY 00
Evaluate results
Solicit action plan(s) from management team Nov 2000
Communicate results and plan of action in specific targeted
areas to all employees
Set baseline and performance criteria